

## Architect's Field Report

201 Park Court, Suite B Ridgeland, MS 39157 P 601.790.9432 F 888.281.0547	28 January 2021  18059-AOI Academy of Innovation / Report Number 054
One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100 P 601.352.5411 F 601.352.5362	Contract Century Construction Date / Time 26 January 2021 / 2:30 PM Weather / Temp Overcast / 68 ° F Est % Complete 85% Sched Conformance + 112 days Work in Progress Paint Work Finish Electrical Other Finish Service Work
161 Lameuse Street, Suite 201 Biloxi, MS 39530 P 228.374.1409 F 228.374.1414	Present at Site Joey Moore, CC Paul Purser, DBA  Observations Arriving on site, I entered the site from the east. Grass has been installed throughout the site and appears in good condition.  At the interior, paint and finish work is ongoing.  At the 2 <sup>nd</sup> floor west side of the building, several double door installations appear to be complete, however, these doors require adjustment. Please review and ensure that doors are installed properly and that all carpentry cuts or adjustments are smooth and finished.
	Items to Verify None Action Required None
	Report By:

Paul Purser, AIA, LEED AP  
Dale | Bailey, an Association

cc: Wilson Little / Joey Moore / Allison Wood (CC)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Will Commarato / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Jerry Montgomery (SM)



Figure 1 – Grass Installed at Site



Figure 2 – Grass Installed at Site



Figure 3 – Grass Installed at Site; Covered Awning Installation Appears Complete



Figure 4 – Clean Up is Ongoing



Figure 5 – Paint is Ongoing



Figure 6 –Finish Electrical is Ongoing (note to check all can lights for flush installation at drywall)



Figure 7 – Paint is Ongoing



Figure 8 – Paint is Ongoing



Figure 9 – Poor Carpentry at Door where cut due to Out of Square Installation



Figure 10 – Installed Double Doors (out of square and need adjustment for proper functionality and aesthetic)



Figure 11 – Installed Double Doors (out of square and need adjustment for proper functionality and aesthetic)



Figure 12 – Installed Double Doors (out of square and need adjustment for proper functionality and aesthetic)



Figure 13 – Installed Double Doors (out of square and need adjustment for proper functionality and aesthetic)



Figure 14 – Progress at Cafeteria