DALE | BAILEY
AN ASSOCIATION

Architect's Field Report

28 May 2020

18050-South Park Elementary / Report Number 010

Contract	Paul Jackson & Son
Date / Time	27 May 2020 / 12:45 PM
Weather / Temp	Clear / 81 ° F
Est % Complete	15%
Sched Conformance	+ 00 days
Work in Progress	Masonry Installation Drywall Work
Present at Site	Wes Gill, Paul Jackson & Son Paul Purser, DBA
Observations	Arriving on site, I met Wes Gill, PJS, near the job site trailer. We discussed CMU block work and drywall mud work. He mentioned that steel joists should be on site in the next couple of weeks.
	A mason was inside the blocked area, cleaning block faces. Drywall finishers were inside floating drywall joints. At the addition, Hollow Metal Jambs have been installed at block wall.
Items to Verify	None
Action Required	None
Report By:	

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Wes Gill (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Abigail Raper / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer / Brian Champlin / Tad Hoffpauir (SDG)

Figure 1 – CMU Block Work

Figure 2 – Brick Ledge for Brick

Figure 3 – Temp Support to be removed

Figure 4 – Electrical Roughed in at CMU

Figure 5 – Water Roughed In

Figure 6 – Rough In Plumbing

Figure 7 – Mud Work at Room 153

Figure 8 – CMU Blocked in at New ADA Restroom

Figure 9 – CMU Blocked in at New ADA Restroom

Figure 10 – Mud Work @ Room 170

Figure 11 – Mud Work @ Room 170

Figure 12 – Mud Work @ Room 114.1