DALE | BAILEY
AN ASSOCIATION

Architect's Field Report

21 November 2020

18053-Vicksburg Junior High School / Report Number 024

Contract	Paul Jackson & Son
Date / Time	20 November 2020 / 1:00 PM
Weather / Temp	Clear / 64 ° F
Est % Complete	48%
Sched Conformance	+ 00 days
Work in Progress	None
Present at Site	Jeff Porter, PJS Paul Purser, DBA
Observations	Arriving on site, I entered from the east parking area. CMU Block work appears to be complete for main structure. Inside, steel has been hung and roofing decking installed throughout.
Items to Verify	None
Action Required	None
Report By:	

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)
       Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
       Gary Bailey / Jason Stewart / Mark Pipper (BPM)
       Russ Blount / Candy Failor (DBA)
       Brandon McKay / Austin Newell (WGK)
       Jason Kackley / Al Guynes (GSK)
       Chris Green / Larry Scott (TPS)
       Tom Schaeffer / Tad Hoffpauir (SDG)

Figure 1 – East Elevation

Figure 2 – East Elevation

Figure 3 – Northeast Elevation Corner


Figure 4 – Entrance Foyer

Figure 5 – Entrance Foyer Structure Installed


Figure 6 – Corridor 202 Structural Work

Figure 7 – Corridor 202 Structural Work

Figure 8 – Corridor 202 Structural Work

Figure 9 – Corridor 202 Structural Work

Figure 10 – Corridor 202 Structural Work

Figure 11 – Corridor 202 Structural Work

Figure 12 – Corridor 202 Structural Work

Figure 13 – Structure above Couns./Vault Area

Figure 14 – Structure above Office Admin Area