

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

26 February 2020

18044-Bovina Elementary / Report Number 002

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 25 February 2020 / 2:44 PM
Weather / Temp Sunny and clear / 66 ° F
Est % Complete 5%
Sched Conformance + 00 days
Work in Progress None
Present at Site School Staff
Paul Purser, DBA

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Observations I arrived on site and reviewed ceiling install after demo. Most grid was up in the southern hall.
Equipment and materials are out back being stored on basketball slab and fenced off.
Items to Verify None
Action Required None
Report By:

Paul Purser, AIA, LEED AP, Partner
Dale | Bailey, an Association

cc: Matthew Goodwin / Richard Creel / Chasity Cupstid (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Jerry Montgomery (SM)



Figure 1 – South Hall Ceiling Grid Installed




Figure 2 – Class Ceiling Installed (Typical)




Figure 3 – Typical Detail at High Windows



Figure 4 – Ensure that these Raceways are Plumb



Figure 5 – Equipment Ready



Figure 6 – Formwork and Rebar on Site