

Architect's Field Report

201 Park Court, Suite B

29 September 2020

Ridgeland, MS 39157

18044-Bovina Elementary / Report Number 025

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

02 October 2020 / 2:00 PM

One Jackson Place, Suite 250

Weather / Temp Clear / 72 ° F

Date / Time

188 East Capitol Street

Jackson, MS 39201-2100

Est % Complete 75%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

F 228.374.1414

Work in Progress None

Present at Site 161 Lameuse Street, Suite 201

Richard Creel, Paul Jackson & Son

Paul Purser, DBA

Biloxi, MS 39530

Observations

Arriving on site, I entered through the rear addition. Glazing has been

P 228.374.1409

installed. Stucco has been finished.

Inside, drywall has been installed at ceilings and a level 1 coat has been

applied.

Items to Verify

None

Action Required

none

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

Matthew Goodwin / Richard Creel / Chasity Cupstid (PJS) Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA) Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

Jerrry Montgomery (SM)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Exterior Work Ongoing



Figure 2 – Glazing in Place; awaiting egress panel




Figure 3 – Stucco Finished at Soffit



Figure 4 – Exterior Finish



Figure 5 – Hard Ceiling Installed and Level 1 Finish Applied



Figure 6 – Hard Ceiling Installed and Level 1 Finish Applied



Figure 7 – Hard Ceiling Installed and Level 1 Finish Applied



Figure 8 – Hard Ceiling Installed and Level 1 Finish Applied



Figure 9 – Hard Ceiling Installed and Level 1 Finish Applied



Figure 10 – Hard Ceiling Installed and Level 1 Finish Applied



Figure 11 – Hard Ceiling Installed and Level 1 Finish Applied



Figure 12 – Hard Ceiling Installed and Level 1 Finish Applied