

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

17 October 2020

18044-Bovina Elementary / Report Number 026

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 14 October 2020 / 9:30 AM
Weather / Temp Clear / 72 ° F
Est % Complete 75%
Sched Conformance + 00 days
Work in Progress None

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Richard Creel, Paul Jackson & Son
Paul Purser, DBA

Observations Arriving on site, I walked the school to review work. Staff bathroom work is ongoing but nearing completion. It appears that the staff toilet in the north hall is in use, however, there are several open electrical outlets that are a hazard to occupancy. If it is the case that school staff is using this space, outlets need to be covered as soon as possible.

At the addition, service workers are installing electrical and hvac.

Items to Verify School Use of Staff Toilet

Action Required Cover Electrical Outlets

Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Matthew Goodwin / Richard Creel / Chasity Cupstid (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Jerry Montgomery (SM)



Figure 1 – Teacher Bathroom in South Hall



Figure 2 – Teacher Bathroom in South Hall



Figure 3 – Hardware at Teacher Bathroom in South Hall



Figure 4 – Hardware at Teacher Bathroom in South Hall



Figure 5 – A New Leak at ceiling Tile Near Class Near Auditorium



Figure 6 – Staff Toilet Appears to be In Use



Figure 7 – Several Electrical Code Violations need to be Remedied ASAP



Figure 8 – Several Electrical Code Violations need to be Remedied ASAP



Figure 9 – Staff Toilet Ceiling Work Appears Ongoing



Figure 10 – Staff Toilet Ceiling Work Appears Ongoing



Figure 11 – Services Work at Hard Ceiling is Ongoing



Figure 12 – Services Work at Hard Ceiling is Ongoing



Figure 13 – Services Work at Hard Ceiling is Ongoing



Figure 14 – Services Work at Hard Ceiling is Ongoing