

Architect's Field Report

201 Park Court, Suite B

21 October 2020

Date / Time

Ridgeland, MS 39157

18044-Bovina Elementary / Report Number 027

P 601.790.9432

Contract Paul Jackson & Son

F 888.281.0547

20 October 2020 / 11:30 AM

One Jackson Place, Suite 250

Weather / Temp Clear / 76 ° F

188 East Capitol Street

Jackson, MS 39201-2100

Est % Complete 75%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

P 228.374.1409

F 228.374.1414

Work in Progress Electrical

Richard Creel, Paul Jackson & Son

Present at Site

Paul Purser, DBA

161 Lameuse Street, Suite 201 Biloxi, MS 39530

Observations

Arriving on site, I entered at the rear addition. Grid work has been

performed. Electrical work is ongoing as electricians were installing

lighting and pulling wire.

Mechanical Units have been set and connected at their respective pads.

Plywood soffit has also been installed at exterior as well as screen to

math existing building detail.

Items to Verify

None

Action Required

None

Report By:

2020.10.2

14:07:48 1/

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

Matthew Goodwin / Richard Creel / Chasity Cupstid (PJS)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Jerrry Montgomery (SM)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – Mech Equipment Installed



Figure 2 – Soffit Plywood Installed



Figure 3 – Mechanical Equipment Installed



Figure 4 – How Will Joint Be Finished?



Figure 5 – Exit Doors Installed



Figure 6 – Grid Installed at Addition




Figure 7 – Grid at Storage Room



Figure 8 – Storage Room



Figure 9 – Grid Installed at Class



Figure 10 – Copy Detail from Grid Corners in Room 101 @ Room 102



Figure 11 – Grid Corners in Room 101



Figure 12 – Grid Installed at Class