

03 July 2020

18045-BOW Bowmar Elementary / Report Number 010

201 Park Court, Suite B

Contract

Paul Jackson & Son

Ridgeland, MS 39157

Date / Time

02 July 2020 / 11:30 AM

P 601.790.9432

Weather / Temp

Clear / 85 ° F

F 888.281.0547

Est % Complete

15%

One Jackson Place, Suite 250

Sched Conformance

+/- 00 days

188 East Capitol Street

Work in Progress

Dir Pad Development

Jackson, MS 39201-2100

Plaster Repair and Paint Prep

P 601.352.5411

Present at Site

Paul Purser, DBA

F 601.352.5362

Observations

Arriving, I entered through the front entrance and noted asbestos abatement protection is still in place for corridor 100. Passing through the Auditorium, I noted door jambs are being staged inside. Along

corridor 115, finishers were preparing plaster and walls for paint.

been completed and is being finished out by the lone excavator.

161 Lameuse Street, Suite 201

Biloxi, MS 39530

P 228.374.1409 F 228.374.1414

I exited the building through Corridor 120 and saw machinery moving

dirt at the additions pad. It appears that the majority of dirt work has

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

James Brock / Jimmy White (PJS)

Chad Shealy / Shaguita Burke / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Corridor 100 Asbestos Abatement Final Stages



Figure 2 – Plaster Repair at Upper Floor



Figure 3 – Paint Prep at Upper Floor



Figure 4 – Door Jambs Staged On Site




Figure 5 – Service Work in Corridor 115 Ongoing




Figure 6 – Service Work in Corridor 115 Ongoing



Figure 7 – Pad Development Nearing Completion




Figure 8 – Corridor 100 Progress