

21 August 2020

18045-BOW Bowmar Elementary / Report Number 012

201 Park Court, Suite B Ridgeland, MS 39157 P 601.790.9432 F 888.281.0547	Contract	Paul Jackson & Son
	Date / Time	20 August 2020 / 11:30 AM
	Weather / Temp	Partly cloudy / 83 ° F
	Est % Complete	35%
One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100 P 601.352.5411 F 601.352.5362	Sched Conformance	+/- 00 days
	Work in Progress	Foundation Layout
	Present at Site	James Brock, Paul Jackson & Son Jimmy White, Paul Jackson & Son Steve Goodwin, Paul Jackson & Son Paul Purser, DBA
161 Lameuse Street, Suite 201 Biloxi, MS 39530 P 228.374.1409 F 228.374.1414	Observations	Arriving on site, I entered through the back-construction gate. James Brock, Jimmy White, & Steve Goodwin were having an onsite meeting discussing footings and foundation work.  Dirt work has been brought to grade and batter boards are set to begin foundation layout.  Pay attention to exposed nails at roof edge trim. So far, nail patterns on trim installed are not neat, orderly, or regular. Exposed fasteners also require sealants or gaskets to prevent water intrusion
	Items to Verify	None
	Action Required	None
	Report By:	

Paul Purser, AIA, LEED AP  
Dale | Bailey, an Association

cc: James Brock / Jimmy White (PJS)  
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)  
Tom Schaeffer / Will Grigg (M)  
Kevin Starks / Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)



Figure 1 – Dirt Pad up to grade



Figure 2 – Batter Boards set and Foundation layout in progress



Figure 3 – Grading Work



Figure 4 – Roof Material Brought Down Over Edge (typical)



Figure 5 – Nail Pattern somewhat neat and regular



Figure 6 – Nail Pattern Uneven and irregular