

## 02 March 2021

## 18045-BOW Bowmar Elementary / Report Number 025

201 Park Court, Suite B

Contract

Paul Jackson & Son

Ridgeland, MS 39157

Date / Time

26 March 2021 / 10:15 AM

P 601.790.9432

Weather / Temp

Observations

Overcast / 65 ° F

F 888.281.0547

Est % Complete 70%

One Jackson Place, Suite 250

**Sched Conformance** 

188 East Capitol Street

Work in Progress Present at Site

Jackson, MS 39201-2100

None Paul Purser, DBA

+/- 00 days

P 601.352.5411

At the interior of the new addition, drywall has been delivered. There

are several areas that rain has still been able to penetrate the façade.

F 601.352.5362

On site, work has been performed on drying in building. Temporary OSB

has been installed at the SE façade. New storefront glazing has been installed at the North corner.

161 Lameuse Street, Suite 201

Biloxi, MS 39530

Items to Verify

P 228.374.1409

**Action Required** 

None

None

F 228.374.1414

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

James Brock / Jimmy White (PJS)

Chad Shealy / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Courtyard at New Addition



Figure 2 – New Storefront Installed



Figure 3 – New Storefront Installed



Figure 4 – NW Facade



Figure 5 – SE Façade; temporary osb installed




Figure 6 – Service Work is Ongoing




Figure 7 – Drywall On Site



Figure 8 – New Storefront Installed