

## Architect's Field Report

201 Park Court, Suite B

07 July 2020

Ridgeland, MS 39157

18048-Redwood Elementary School / Report Number 005

P 601.790.9432 F 888.281.0547

Contract Harris Construction

Date / Time

06 July 2020 / 2:10 PM

One Jackson Place, Suite 250

Weather / Temp

**,** 

188 East Capitol Street

Est % Complete

5%

Jackson, MS 39201-2100 P 601.352.5411

it /0 Complete 3/

Clear / 86 ° F

Sched Conformance + 00 days

F 601.352.5362

Work in Progress Concrete Install

Roofing Installation Fire Alarm Install

161 Lameuse Street, Suite 201

Biloxi, MS 39530 Present at Site

Michael Byrd, Harris Construction

P 228.374.1409

Paul Purser, DBA

F 228.374.1414

Arriving, I entered the building at the main entrance. At this entrance,

workers were pumping out water in the excavated areas. Inside,

electricians were installing fire alarm cable.

VCT installers were working in the north hall of the main building.

Roofers were working on this side of the structure.

Items to Verify

Observations

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: David Harris / Michael Byrd (HC)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Ebony Batchelor / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – Formwork Begun @ Ramp



Figure 2 – Formwork Structure




Figure 3 – New Damage at new Ceiling Noted in Main Hall



Figure 4 – Core drilling at Bathroom for new Drains



Figure 5 – VCT Flooring Installed




Figure 6 – VCT Flooring Installed