

## Architect's Field Report

201 Park Court, Suite B Ridgeland, MS 39157 P 601.790.9432 F 888.281.0547	12 June 2020  18050-South Park Elementary / Report Number 012
One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100 P 601.352.5411 F 601.352.5362	Contract Paul Jackson & Son Date / Time 09 June 2020 / 2:30 PM Weather / Temp Cloudy / 83 ° F Est % Complete 20% Sched Conformance + 00 days Work in Progress Steel Truss Install
161 Lameuse Street, Suite 201 Biloxi, MS 39530 P 228.374.1409 F 228.374.1414	Present at Site Wes Gill, Paul Jackson & Son OAC Attendees Paul Purser, DBA Observations After our monthly meeting, I reviewed progress. Steel Truss installation was occurring and nearing completion.  Travis Altsman, DBA, and I reviewed with the flooring installer VCT installation at the entry foyers at both sides of the cafeteria. There is some limited VCT repair to be made inside of the cafeteria that we discussed, primarily one continuous line of VCT to match the foyers in a single row as noted in Figure 1.
	Items to Verify None Action Required None
	Report By:

Paul Purser, AIA, LEED AP  
Dale | Bailey, an Association

cc: Austin Stults / Wes Gill (PJS)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Abigail Raper / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Tom Schaeffer / Brian Champlin / Tad Hoffpaur (SDG)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – VCT to be replaced in single row at damage in this photo



Figure 2 – VCT to be removed to threshold and ceramic tiled overlaid with new VCT



Figure 3 – Truss Installation



Figure 4 – Truss Installation