

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

27 August 2020

18053-Vicksburg Junior High School / Report Number 017

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 26 August 2020 / 4:45 PM
Weather / Temp Partly cloudy / 90 ° F
Est % Complete 24%
Sched Conformance + 00 days
Work in Progress None

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Paul Purser, DBA

Observations Arriving on site, I reviewed work at the addition. Footing trenching has begun but will be on hold due to incoming rain for another week.
There is an issue with erosion beneath the stair at the north side of the addition that needs to be addressed soon.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer / Tad Hoffpauir (SDG)



Figure 1 – Rebar and Structural Steel Stored on Site



Figure 2 – Waddles in Place at Storm Sewer



Figure 3 – Trench Before rain



Figure 4 – Trenched Out Footings



Figure 5 – Footings



Figure 6 – Erosion at North Side of Addition