

Architect's Field Report

201 Park Court, Suite B

02 October 2020

Ridgeland, MS 39157

18053-Vicksburg Junior High School / Report Number 021

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

29 September 2020 / 4:15 PM

One Jackson Place, Suite 250

Weather / Temp Clear

188 East Capitol Street

Clear / 73 ° F

Jackson, MS 39201-2100

Est % Complete 48%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress None

Date / Time

ivone

161 Lameuse Street, Suite 201

Present at Site Jeff Porter, PJS

Paul Purser, DBA

Biloxi, MS 39530

Observations Arriving on

P 228.374.1409 F 228.374.1414 Arriving on site, I walked the addition to review concrete progress. Reinforcing is in place and slab is ready for concrete. The Stair near this

area has been filled with slurry to protect from further erosion.

Items to Verify

Action Required

None None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Reinforcing @ Slab Pour



Figure 2 – Footing Reinforcing



Figure 3 – Footing Reinforcing



Figure 4 – Northeast Edge of Slab



Figure 5 – Eroded Dirt Filled



Figure 6 – Northwest Edge of Slab