

## Architect's Field Report

201 Park Court, Suite B

Ridgeland, MS 39157

P 601.790.9432

F 888.281.0547

Paul Jackson & Son

Date / Time One Jackson Place, Suite 250

> Weather / Temp 188 East Capitol Street

Jackson, MS 39201-2100

P 601.352.5411

F 601.352.5362

161 Lameuse Street, Suite 201

Biloxi, MS 39530

P 228.374.1409

F 228.374.1414

28 May 2021

18056-Warren Central Junior High School / Report Number 023

Contract

26 May 2021 / 1:00 PM

Cloudy / 75 ° F

Est % Complete 75%

Sched Conformance + 00 days

Work in Progress Tile, Painting, Door Install, Concrete Forming

Present at Site Jay Wilson, Paul Jackson & Son

Paul Purser, DBA

Observations Arriving on site, I entered at the front entry. Finishing is nearing

completion at the admin area. Doors were being installed and hardware

as well.

At the cafeteria extension, significant water was on the floor. I spoke with Jay Wilson about the issue and he stated that some flashing is still unfinished at the roof but will be completed with parapet trim is

installed.

At the field house, painters were applying their product to the field

house floor. In the shower area, tile has been installed.

Items to Verify None **Action Required** None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

Austin Stults / Tim Wilson / Kipp Ready (PJS) Chad Shealy / Christi Kilroy (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Candy Failor (DBA) Brandon McKay / Austin Newell (WGK) Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS) Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Progress at Entry



Figure 2 – Progress at Entry



Figure 3 – Admin Area with Grid Installed



Figure 4 – Cafeteria Extension




Figure 5 – Water Noted in cafeteria extension due to roof unfinished roof flashing



Figure 6 – Sidewalk Formed (vegetation should be removed before concrete installed)



Figure 7 – Floor Paint at Field House



Figure 8 – Tile at Field House



Figure 9 – Tile at Field House



Figure 10 – Sidewalk Formed