

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

25 September 2020

18053-Vicksburg Junior High School / Report Number 020

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Paul Jackson & Son  
Date / Time 23 September 2020 / 2:00 PM  
Weather / Temp Overcast / 70 ° F  
Est % Complete 48%  
Sched Conformance + 00 days  
Work in Progress None  
Present at Site Jeff Porter, PJS  
Paul Purser, DBA

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Observations Arriving on site, I reviewed work performed at addition foundation area. Footings have been poured and rebar is in place for upcoming slab pour. These rebar ends are not protected and need to be capped. Caution tape has been wrapped around slab area. Plastic is also in place in preparation for slab pour.

Items to Verify None  
Action Required None

Report By:

Paul Purser, AIA, LEED AP  
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Tom Schaeffer / Tad Hoffpaur (SDG)



Figure 1 – Concrete Footings Poured at Addition North



Figure 2 – Preparation for Slab Pour is ongoing





Figure 3 – Preparation for Slab Pour is ongoing



Figure 4 – Preparation for Slab Pour is ongoing






Figure 5 – Preparation for Slab Pour is ongoing



Figure 6 – Connection between first pour and upcoming pour