

Architect's Field Report

201 Park Court, Suite B

30 September 2021

Ridgeland, MS 39157

18053-Vicksburg Junior High School / Report Number 038

P 601.790.9432 F 888.281.0547

Contract Paul Jackson & Son

30 September 2021 / 12:30 AM

One Jackson Place, Suite 250

Weather / Tomp

Weather / Temp

Date / Time

Overcast / 80 ° F

188 East Capitol Street Jackson, MS 39201-2100

Est % Complete 98%

P 601.352.5411

Sched Conformance + 90 days

F 601.352.5362

Work in Progress Masonry, Awning Work

1 001.332.3302

Present at Site Paul Purser, DBA

161 Lameuse Street, Suite 201

Observations

Biloxi, MS 39530

Work is in progress at the exterior. The lintel over the entry has been

P 228.374.1409

partially removed. Fence work is still underway at a couple of locations

and the awning is nearing completion.

F 228.374.1414

At the interior, the central handrail at the grand stair is installed. Work

continues elsewhere at other handrails.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com baileyarch.com

Architects Who Know Education




Figure 1 – Partial Lintel Removed for Correction



Figure 2 – Fence work is Ongoing



Figure 3 – Awning is Ongoing




Figure 4 – Central handrail Installed



Figure 5 – Fence work is Ongoing