

Architect's Field Report

201 Park Court, Suite B

31 December 2020

Date / Time

Ridgeland, MS 39157

18057-Warrenton Elementary / Report Number 006

P 601.790.9432

F 888.281.0547 Contract KT Builder

29 December 2020 / 11:30 AM

One Jackson Place, Suite 250

Weather / Temp Clear / 62 ° F

188 East Capitol Street

Est % Complete 80%

Jackson, MS 39201-2100

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress None

Paul Purser, DBA

161 Lameuse Street, Suite 201

Present at Site

Biloxi, MS 39530

P 228.374.1409 F 228.374.1414 On site, I saw some work performed at both ADA ramp locations.

Concrete has been installed for ramp support at out door classroom.

Metal Welding plates are embedded.

At the long ramp in between 2 central buildings has been laid out and

staked off.

Items to Verify

Observations

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: Hunter McNeer / Walt Swider (KT)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Ebony Batchelor / Candy Failor (DBA)

Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Concrete Pour for ADA Ramp Install



Figure 2 – Concrete Pour for ADA Ramp Install



Figure 3 – ADA Ramp Layout Staked Off



Figure 4 – ADA Ramp Layout Staked Off