

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

26 September 2019

18043-BW Beechwood Elementary / Report Number 001

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Thrash Construction
Date / Time 25 September 2019 / 2:00 PM
Weather / Temp Clear / 93 ° F
Est % Complete 2%
Sched Conformance +/- 00 days
Work in Progress Dirt Work for Parking Area / Ceiling Grid Demo
Present at Site Jason McCoy, Thrash Construction
Leslie Mallette, Caydens Construction
Paul Purser, DBA

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Observations Dirt work for parking area has been dug and compacted for 60% of the parking lot. Digging continues on other 40%.
Interior ceiling demolition has begun in kindergarten section of school. Ceiling tile has been removed.
Items to Verify Ladner Testing has been scheduled for Inspection
Action Required None

Report By:

paul purser, AIA, LEED AP, Partner
Dale | Bailey, an Association

cc: Luke Walker (TC)
Chad Shealy / Shaquita Burke (VWSD)
Gary Bailey / Jason Stewart (BPM)
Russ Blount / Shelby Mitchell / Candy Failor (DBA)



Figure 1 – Parking Area Compaction Work



Figure 2 – Parking Area Digging Work



Figure 3 – Area Lined Out For Compacter Concrete Slab



Figure 4 – Removed Ceiling Tile, Typical Demo Performed in 5 Rooms



Figure 5 – Power Still Connected for Clients Use of the Room