

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

06 November 2019

18043-BW Beechwood Elementary / Report Number 008

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Thrash Construction
Date / Time 05 November 2019 / 4:00 PM
Weather / Temp Clear / 72 ° F
Est % Complete 15%
Sched Conformance +/- 00 days
Work in Progress None

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site School Receptionists
Paul Purser, DBA
Shelby Mitchell, DPA

Observations Arriving, I walked Building 1 to note any changes. Ceiling Tile work remains in high ceiling, Class 115, and restrooms.

I Met Shelby Mitchell in Corridor 206 to discuss hardware for 3 doors.

Together, Shelby and I reviewed Building 1 work. We determined Damage noted in Figure 11 of Field Report dated 10/25/2019 to be a result of reconfiguring lights off drywall. This damage should be addressed when walls are paint in future work.

We also walked building 3 to review demolition.

I spoke with receptionist and asked if issues with sound that we spoke of on our last site visit were still occurring and she indicated that they were not an issue of which she was aware.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner
Dale | Bailey, an Association

cc: Luke Walker (TC)
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)
Gary Bailey / Jason Stewart / Mark Pippet (BPM)
Russ Blount / Shelby Mitchell / Candy Failor (DBA)
Blake Mendrop (M)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)



Figure 1 – Grid in Restrooms



Figure 2 – Note Speakers are Pre-existing Condition



Figure 3 – Building 3 Demo



Figure 4 – Note Supply @ Upper Walls (typical)



Figure 5 – Speakers Exist Prior to Reinstallation of Grid & Tile



Figure 6 – Building 3 Corridor Demolition