

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

24 March 2020

18043-BW Beechwood Elementary / Report Number 027

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Thrash Construction
Date / Time 24 March 2020 / 1:00 PM
Weather / Temp Sunny and clear / 74 ° F
Est % Complete 71%
Sched Conformance +/- 00 days
Work in Progress Paint

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site H&A Painting
Paul Purser, DBA

Observations I arrived on site to review work. Painters were on lunch break. Paint touch ups are in progress.

Demolition work is on-going at the exterior NE section of the building. Concrete has been removed as well as the awning.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner
Dale | Bailey, an Association

cc: Luke Walker (TC)
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Shelby Mitchell / Candy Failor (DBA)
Blake Mendrop (M)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)



Figure 1 – Prime Patches at Wall Repairs




Figure 2 – Prime Patches at Wall Repairs




Figure 3 – Prime Patches at Wall Repairs



Figure 4 – Are these panels to be painted?



Figure 5 – Concrete & Awning Demolition



Figure 6 – Concrete & Awning Demolition