

## 07 April 2020

## 18043-BW Beechwood Elementary / Report Number 029

201 Park Court, Suite B Contract Thrash Construction

Ridgeland, MS 39157 Date / Time 06 April 2020 / 12:00 PM

P 601.790.9432 Weather / Temp Overcast / 70 ° F

F 888.281.0547

Est % Complete 75%

One Jackson Place. Suite 250 Sched Conformance +/- 00 days

188 East Capitol Street Work in Progress Ceiling Tile Work

Jackson, MS 39201-2100 Present at Site Lay in Tile Crew Paul Purser, DBA

F 601.352.5362 Observations I arrived on site and reviewed final Installation of Ceiling Grid. There are

smudges, etc. on wall that require cleaning.

161 Lameuse Street, Suite 201 Gym Floor Threshold has been installed, is level and continuous.

Biloxi, MS 39530 Items to Verify None
P 228.374.1409 Action Populated None

P 228.374.1409 Action Required None F 228.374.1414 P .... R

Report By:

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Luke Walker (TC)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Shelby Mitchell / Candy Failor (DBA)

Blake Mendrop (M)

Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com Architects Who Know Education



Figure 1 – Some Tape Left; Also Coverage to left of tape not complete



Figure 2 – Dirt Hand Marks (most likely from ceiling install)



Figure 3 – Dirty Marks on Wall




Figure 4 – Threshold Installed at Gym Floor