

21 April 2020

18043-BW Beechwood Elementary / Report Number 031

201 Park Court, Suite B Contract Thrash Construction

Ridgeland, MS 39157 Date / Time 20 April 2020 / 3:30 PM

P 601.790.9432 Weather / Temp Sunny / 68 ° F

F 888.281.0547

Est % Complete 75%

One Jackson Place. Suite 250 Sched Conformance +/- 00 days

188 East Capitol Street Work in Progress None

Jackson, MS 39201-2100 Present at Site Paul Purser, DBA

P 601.352.5411 Observations I arrived on site and reviewed work on exterior. I attempted to go inside

but no one was there working and the building was locked. Concrete is satisfactory. Dirt in some places needs to be graded to upper edge of

walk.

161 Lameuse Street, Suite 201

F 601.352.5362

Biloxi, MS 39530 Items to Verify None
P 228.374.1409 Action Required None

F 228.374.1414 Report By:

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Luke Walker (TC)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Shelby Mitchell / Candy Failor (DBA)

Blake Mendrop (M)

Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – Concrete Junction where new meets old



Figure 2 – Extent of Metal Awning



Figure 3 – Concrete Forming



Figure 4 – Clean up edge of concrete that overhangs here (North Corner of Awning/walkway)



Figure 5 – Concrete Sidewalk Complete (dirt needs to be graded back to edge of walk)



Figure 6 – Concrete Sidewalk Complete (dirt needs to be graded back to edge of walk)