

## 23 April 2020

18043.01-BWF Beechwood Elementary / Report Number 001

201 Park Court, Suite B	Contract	Live Oak Construction
Ridgeland, MS 39157	Date / Time	22 April 2020 / 2:15 PM
P 601.790.9432 F 888.281.0547	Weather / Temp	Overcast / 66 ° F
1 000.201.0047	Est % Complete	5%
One Jackson Place, Suite 250	Sched Conformance	+/- 00 days
188 East Capitol Street	Work in Progress	Paint Work
Jackson, MS 39201-2100	Present at Site	Paint Crew
P 601.352.5411		Paul Purser, DBA
F 601.352.5362	Observations	Arriving on site, I walked building 3 to review work. Painters were at work in some classrooms on the Northwest Side of the Building. I walked
161 Lameuse Street, Suite 201		Building 2 and 1 and did not notice any changes. Work is ongoing in most areas.
Biloxi, MS 39530	Items to Verify	None
P 228.374.1409	3	
F 228.374.1414	Action Required	None
	Report By:	

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Ron Hall / Richard Thompson (LOC) Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Abigail Raper / Candy Failor (DBA)



Figure 1 – Building 3 North Space



Figure 2 – Classroom Painted



Figure 3 – North Side of Building 3 Bathroom Hall




Figure 4 –Electrical Box Panels




Figure 5 – North Side of Building 3 Bathroom Hall



Figure 6 – North Bathroom Painted




Figure 7 – This Line needs to be Straightened



Figure 8 – North Admin Rooms



Figure 9 – SW Section of Building 3



Figure 10 – South Bathroom Area



Figure 11 – South Bathroom Area



Figure 12 – Bathroom Painting Ongoing



Figure 13 – East Section of Building 3



Figure 14 – Principals Office Entry Room