

01 May 2020

18043.01-BWF Beechwood Elementary / Report Number 003

201 Park Court, Suite B	Contract	Live Oak Construction
Ridgeland, MS 39157	Date / Time	30 April 2020 / 12:30 PM
P 601.790.9432	Weather / Temp	Clear / 71 ° F
F 888.281.0547	Est % Complete	5%
One Jackson Place, Suite 250	Sched Conformance	+/- 00 days
188 East Capitol Street	Work in Progress	Paint Work
Jackson, MS 39201-2100	Present at Site	Paint Crew
P 601.352.5411		Paul Purser, DBA
F 601.352.5362	Observations	Arriving on site, I walked building 3 to review work. Painters were working between bathrooms and classrooms. There are a few rooms
161 Lameuse Street, Suite 201		that appear to be completed but there are some prep issues in most of these (ie glue on wall and painted over; holes not patched as is standard
Biloxi, MS 39530		paint prep).
P 228.374.1409	Items to Verify	None
F 228.374.1414	Action Required	None
	Report By:	

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: Ron Hall / Richard Thompson (LOC) Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Abigail Raper / Candy Failor (DBA)



Figure 1 – Building 3 Paint Ongoing



Figure 2 – Glues and adhesives should be removed prior to painting



Figure 3 – Holes should be filled prior to painting



Figure 4 – Base Removal is ongoing