

04 June 2020

18043.01-BWF Beechwood Elementary / Report Number 005

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

Contract Live Oak Construction
Date / Time 03 June 2020 / 1:30 PM
Weather / Temp Cloudy / 83 ° F
Est % Complete 39%

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Sched Conformance +/- 00 days
Work in Progress Paint Work

Present at Site Ronald Hall, Live Oak Construction
Curtis Brown, Premier One Painting
Paul Purser, DBA

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Observations Arriving, I began my walk in the North wing (300 wing). Paint is ongoing here. Touchups and Trim Remain incomplete.

Flooring in this wing has begun. There are several rooms that have been laid and some tiles have been installed that are discolored; these should be removed, disposed, and replaced with matching tiles.

Some Painting has begun in the 100 Wing in some classrooms.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Ron Hall / Richard Thompson (LOC)
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Abigail Raper / Candy Failor (DBA)



Figure 1 – Painting in the 300 Wing is Ongoing




Figure 2 – Painting in the 300 Wing is Ongoing



Figure 3 – Painting in the 300 Wing is Ongoing



Figure 4 – Painting in the 300 Wing is Ongoing



Figure 5 – VCT Flooring Install is Ongoing at the 300 Wing



Figure 6 – Off-Colored Tiles Should be Culled



Figure 7 – Off-Colored Tiles Should be Culled



Figure 8 – Paint is Ongoing in 300 Wing



Figure 9 – Floor Prep Noted



Figure 10 – Off-Colored Tiles Should be Culled