

26 June 2020

18043.01-BWF Beechwood Elementary / Report Number 007

201 Park Court, Suite B Ridgeland, MS 39157 P 601.790.9432 F 888.281.0547	Contract	Live Oak Construction
	Date / Time	24 June 2020 / 11:45 AM
	Weather / Temp	Clear / 79 ° F
	Est % Complete	45%
One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100 P 601.352.5411 F 601.352.5362	Sched Conformance	+/- 00 days
	Work in Progress	Paint Work Floor Installation
	Present at Site	Paul Purser, DBA
161 Lameuse Street, Suite 201 Biloxi, MS 39530 P 228.374.1409 F 228.374.1414	Observations	Arriving, I entered through the Lobby nearest Building 100. The Flooring Installer was in Building 200, working on the Library Floor. Painters were in Building 100, working in and on classrooms. Another Flooring Installer was finishing up in Building 300.
	Items to Verify	None
	Action Required	None
	Report By:	

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Ron Hall / Richard Thompson (LOC)
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Abigail Raper / Candy Failor (DBA)



Figure 1 – Paint is Ongoing in Building 100



Figure 2 – Paint Work in Main Corridor Space for Building 100



Figure 3 – Paint on Door Noted in Building 100



Figure 4 – Floor Installation at Building 200



Figure 5 – Floor Installation at Building 200 in Library



Figure 6 – Contractor Taking Care to Work around School Property



Figure 7 – Corridor Flooring in Building 300 is Ongoing



Figure 8 – Corridor Flooring in Building 300 is Ongoing