

## 03 July 2020

18043.01-BWF Beechwood Elementary / Report Number 008

201 Park Court, Suite B	Contract	Live Oak Construction
Ridgeland, MS 39157	Date / Time	02 July 2020 / 2:15 PM
P 601.790.9432	Weather / Temp	Clear / 85 ° F
F 888.281.0547	Est % Complete	45%
One Jackson Place, Suite 250	Sched Conformance	+/- 00 days
188 East Capitol Street	Work in Progress	Paint Work
Jackson, MS 39201-2100		Floor Installation
P 601.352.5411	Present at Site	Paul Purser, DBA
F 601.352.5362	Observations	I arrived on site and entered in Lobby on East Side. There is demolished Wood in this room that has recently been finished with nails face down into new floor. This floor should be protected is used to stored material.
161 Lameuse Street, Suite 201		ľ
Biloxi, MS 39530		Painting is ongoing. Door Jambs in all areas still require painting as well as all Lockers. Walls in building 100 are around 50% complete.
P 228.374.1409		° .
F 228.374.1414		The only people on site were the flooring installer and his helper.
	Items to Verify	None
	Action Required	None
	Report By:	

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: Ron Hall / Richard Thompson (LOC) Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Abigail Raper / Candy Failor (DBA)

dalepartners.com baileyarch.com Architects Who Know Education



Figure 1 – New Floor in Lobby is Unprotected from Contractor's Demo



Figure 2 – Building 100 Painting is about Halfway Complete



Figure 3 – Building 100



Figure 4 – Building 100: Prep still Required in Some Areas that are Painted



Figure 5 – Building 100 Vestibule



Figure 6 – Corridor at Building 100




Figure 7 – Library Floor Installed




Figure 8 – Classroom 207 New Floor