

29 April 2020

18045-BOW Bowmar Elementary / Report Number 003

201 Park Court, Suite B

B Contract

Paul Jackson & Son

Ridgeland, MS 39157

Date / Time

28 April 2020 / 2:30 PM

P 601.790.9432

Weather / Temp

Overcast / 74 ° F

F 888.281.0547

Est % Complete
Sched Conformance

2%

One Jackson Place, Suite 250

Building Demo

+/- 00 days

188 East Capitol Street

Work in Progress

Interior Ceiling Demolition

Jackson, MS 39201-2100 P 601.352.5411

Electrical Repair

F 601.352.5362

Auditorium Chair Removal

.352.5362

James Brock, Paul Jackson & Son

Present at Site

Travis Altsman, DBA

161 Lameuse Street, Suite 201

Biloxi, MS 39530

Observations

Paul Purser, DBA

Arriving on site, I noted demo work at rear trailer area. Work is about

60% complete here.

P 228.374.1409 F 228.374.1414

I met Travis Altsman, DBA and James Brock, PJS as well as Paul Jackson & Sons Finish Subcontractor inside, where we discussed plaster repairs.

Interior ceiling demo is underway as well as the removal of chairs at the

auditorium.

I met the electrician in the hall who mentioned that the Main feeder for power running through the north hall was unsupported by anything

other than the ceiling that was being demoed.

Items to Verify

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP, Partner Dale | Bailey, an Association

cc: James Brock / Jimmy White (PJS)

Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)

Tom Schaeffer / Will Grigg (M)

Kevin Starks / Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – Demo Work at Trailers



Figure 2 – Demo Work at Trailers




Figure 3 – Ceiling Tile Removed




Figure 4 – Ceiling Demo has commenced



Figure 5 – Some Protection in place for windows



Figure 6 – Wire through wall is not in conduit