

02 October 2020

18045-BOW Bowmar Elementary / Report Number 016

201 Park Court, Suite B Ridgeland, MS 39157 P 601.790.9432 F 888.281.0547	Contract	Paul Jackson & Son
	Date / Time	29 September 2020 / 3:30 PM
	Weather / Temp	Clear / 73 ° F
	Est % Complete	35%
One Jackson Place, Suite 250 188 East Capitol Street Jackson, MS 39201-2100 P 601.352.5411 F 601.352.5362	Sched Conformance	+/- 00 days
	Work in Progress	Seating Installation
	Present at Site	Jimmy White, Paul Jackson & Son Paul Purser, DBA
	Observations	Arriving on site, I entered at the auditorium. Seating Installation continues in this area. At the corridors, grid work has been performed and is ongoing. At the rear addition, trenching and footing installation is ongoing.
161 Lameuse Street, Suite 201 Biloxi, MS 39530 P 228.374.1409 F 228.374.1414	Items to Verify	None
	Action Required	None
	Report By:	

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: James Brock / Jimmy White (PJS)
Chad Shealy / Shaquita Burke / Bill Sanderford (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Travis Altsman / Abigail Raper / Candy Failor (DBA)
Tom Schaeffer / Will Grigg (M)
Kevin Starks / Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)



Figure 1 – Auditorium Seating Installation



Figure 2 – Grid Install



Figure 3 – Grid Install



Figure 4 – Grid Install



Figure 5 – Grid Install



Figure 6 – Grid Install with Reveal for Glazing



Figure 7 – Footing Trenches



Figure 8 – Footing Trenches



Figure 9 – Footing Trenches



Figure 10 – Footing Trenches



Figure 11 – Footing Trenches



Figure 12 – Grid Install at Hallway Junction



Figure 13 – Grid Install @ Furr-Down



Figure 14 – Grid Install @ Furr-Down



Figure 15 – Grid Install



Figure 16 – Grid Install