

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

23 May 2020

18048-Redwood Elementary School / Report Number 001

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Harris Construction
Date / Time 21 May 2020 / 5:30 PM
Weather / Temp Clear / 86 ° F
Est % Complete 1%
Sched Conformance + 00 days
Work in Progress None

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Paul Purser, DBA

Observations Arriving on site, I entered at main entry (section A, south Hall). I walked the main corridor where demo had begun. I spoke with Michael Byrd prior to my visit and he mentioned that their company had just begun on site.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: David Harris / Michael Byrd (HC)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Travis Altsman / Ebony Batchelor / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)



Figure 1 – Ceiling Demo Progress (Main Entry)



Figure 2 – Ceiling Demo Progress (Main Entry)



Figure 3 – Ceiling Demo Progress (Classrooms on South Section of Building)



Figure 4 – Ceiling Demo Progress (Can these comm wires be temporarily supported to protect from damage?)



Figure 5 – Ceiling Demo Progress (Classrooms on South Section of Building)



Figure 6 – Ceiling Demo Progress (Section A N/S Hall)



Figure 7 – Ceiling Demo Progress (Classrooms on South Section of Building)



Figure 8 – Ceiling Demo Progress (Classrooms on South Section of Building)



Figure 9 – Ceiling Demo Progress (Classrooms on South Section of Building)



Figure 10 – Ceiling Demo Progress (Section A N/S Hall)



Figure 11 – Ceiling Demo Progress (Section A North Hall)



Figure 12 – Ceiling Demo Progress (Classrooms on North Section of Building)



Figure 13 – Ceiling Demo Progress (Classrooms on North Section of Building)



Figure 14 – Ceiling Demo Progress (Classrooms on North Section of Building)



Figure 15 – North Section of Building



Figure 16 – Dumpster Located at Front parking Lot