

## Architect's Field Report

201 Park Court, Suite B

05 August 2020

Ridgeland, MS 39157

18048-Redwood Elementary School / Report Number 006

P 601.790.9432 F 888.281.0547

Contract Harris Construction

04 August 2020 / 2:00 PM

One Jackson Place, Suite 250

Date / Time

188 East Capitol Street

Sunny and clear / 90 ° F

Jackson, MS 39201-2100

Est % Complete 50%

P 601.352.5411

**Sched Conformance** + 00 days

F 601.352.5362

Work in Progress Formwork Demolition

Finish Plumbing

**Toilet Partitions Installation** 

161 Lameuse Street, Suite 201

Present at Site

Weather / Temp

Michael Byrd, Harris Construction

Biloxi, MS 39530 P 228.374.1409

Paul Purser, DBA

F 228.374.1414

Observations I arrived on site and entered through main entry. Concrete Formboards

have been removed here.

Inside, bathroom work was on ongoing. Tile work is mostly complete and acceptable. Toilet Fixtures are installed and one bathroom has toilet

partitions.

Concrete Sidewalks have been poured at the exterior and are complete.

Items to Verify

None

**Action Required** 

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

cc: David Harris / Michael Byrd (HC)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Ebony Batchelor / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS)

dalepartners.com

baileyarch.com

Architects Who Know Education



Figure 1 – Entry Concrete Work




Figure 2 – Tile Installed at Bathrooms



Figure 3 – Tile Installed at Bathrooms



Figure 4 – Fixtures Installed



Figure 5 – Fixtures Installed



Figure 6 – Fixtures Installed



Figure 7 – New Damage at new Ceiling Noted in Main Hall




Figure 8 – Tile Installed at Bathrooms



Figure 9 – Tile Installed at Bathrooms




Figure 10 – Partitions and Fixtures Installed



Figure 11 – Concrete Sidewalks Installed



Figure 12 – Concrete Sidewalks Installed



Figure 13 – Concrete Sidewalks Installed



Figure 14 – Concrete Sidewalks Installed



Figure 15 – Concrete Sidewalks Installed



Figure 16 – Concrete Sidewalks Installed



Figure 17 – Concrete Sidewalks Installed



Figure 18 – Concrete Sidewalks Installed



Figure 19 – Concrete Sidewalks Installed



Figure 20 – Concrete Sidewalks Installed



Figure 21 – Concrete Sidewalks Installed



Figure 22 – Concrete Sidewalks Installed