

Architect's Field Report

201 Park Court, Suite B

31 December 2020

Ridgeland, MS 39157

18048-Redwood Elementary School / Report Number 008

P 601.790.9432

F 888.281.0547 Contract

Harris Construction

One Jackson Place, Suite 250

Date / Time 29 December 2020 / 3:15 PM

188 East Capitol Street

Weather / Temp Clear / 65 ° F

Jackson, MS 39201-2100

Est % Complete 75%

P 601.352.5411

Sched Conformance + 00 days

F 601.352.5362

Work in Progress **Painting**

161 Lameuse Street, Suite 201

Present at Site Paul Purser, DBA

Biloxi, MS 39530

On site, I noted paint prep performed at hall interiors.

P 228.374.1409 F 228.374.1414 Handrails have been painted at the front entries but do need some touch

up where paint is missing.

Items to Verify

Observations

None

Action Required

None

Report By:

Paul Purser, AIA, LEED AP Dale | Bailey, an Association

David Harris / Michael Byrd (HC)

Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)

Gary Bailey / Jason Stewart / Mark Pipper (BPM)

Russ Blount / Travis Altsman / Ebony Batchelor / Candy Failor (DBA)

Brandon McKay / Austin Newell (WGK)

Jason Kackley / Al Guynes (GSK)

Chris Green / Larry Scott (TPS)

dalepartners.com baileyarch.com

Architects Who Know Education



Figure 1 – Paint Prep at Halls



Figure 2 – Paint Prep at Halls



Figure 3 – Paint Prep at Halls



Figure 4 – Handrail paint is Ongoing



Figure 5 – Handrail paint is Ongoing




Figure 6 – Handrail paint is Ongoing



Figure 7 – Handrail paint is Ongoing




Figure 8 – Rock Installed at Planter