

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

03 March 2020

18053-Vicksburg Junior High School / Report Number 001

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 02 March 2020 / 4:45 PM
Weather / Temp Cloudy / 70 ° F
Est % Complete 2%
Sched Conformance + 00 days
Work in Progress Asbestos Abatement
Ceiling Demo

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Dan Duvall (PJS)
Paul Purser, DBA

Observations Arriving on site, I met Dan Duvall, PJS. He was serving as superintendent while Jeff Porter was in OSHA Classes. We walked the project together.

Abatement at building to be demolished is near completion. Ceiling tile and grid removal is on-going.

2nd Floor Bathroom demolition has been performed.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP, Partner
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Chasity Cupstid (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer (SDG)



Figure 1 – Building Abatement before Demolition



Figure 2 – Building Abatement before Demolition



Figure 3 – Building Abatement before Demolition



Figure 4 – Building Abatement before Demolition



Figure 5 – Ceiling Tiles and Grid Removal at 2nd Floor



Figure 6 – Ceiling Tiles and Grid Removal at 2nd Floor



Figure 7 – Bathroom Demo at 2nd Floor E-217A



Figure 8 – Bathroom Demo at 2nd Floor E-217B



Figure 9 – Temp Wall to Block Construction at Second Floor



Figure 10 – Ceiling Tile Removal On-Going



Figure 11 – Ceiling Tile Removal at Second Floor Classrooms



Figure 12 – Ceiling Tile Removal at Second Floor Classrooms



Figure 13 – Ceiling Tile Removal at Second Floor Classrooms



Figure 14 – Ceiling Tile Removal at Second Floor Classrooms




Figure 15 – Ceiling Tile & Grid Removal at First Floor



Figure 16 – Ceiling Tile & Grid Removal at First Floor Bathrooms



Figure 17 – Ceiling Tile Removal at First Floor Classrooms



Figure 18 – Ceiling Tile Removal at First Floor Classrooms



Figure 19 – Ceiling Tile & Grid Removal at First Floor



Figure 20 – Ceiling Tile Removal at First Floor