

Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

24 March 2020

18053-Vicksburg Junior High School / Report Number 003

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Paul Jackson & Son  
Date / Time 24 March 2020 / 10:45 PM  
Weather / Temp Sunny intervals / 76 ° F  
Est % Complete 3%  
Sched Conformance + 00 days  
Work in Progress Building Demolition  
Floor Base Removal  
HVAC Duct Removal

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Present at Site Dan Duvall (PJS)  
Paul Purser, DBA

Observations I arrived and entered at front entry. Floor base and duct removals were in progress. I spoke with Mr. Dan Duvall (PJ&S). He mentioned that HVAC duct is their primary task right now as well as the ongoing building demo.

Items to Verify None

Action Required None

Report By:

Paul Purser, LEED AP  
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Tom Schaeffer (SDG)



Figure 1 –Front Entry Ceiling Demoed



Figure 2 – Front Office Ceiling Demoed




Figure 3 – Floor Base Removal in Progress




Figure 4 – HVAC Duct Demo In Progress



Figure 5 – Building Demo is OnGoing



Figure 6 – Building Demolition