

## Architect's Field Report

201 Park Court, Suite B  
Ridgeland, MS 39157  
P 601.790.9432  
F 888.281.0547

29 April 2020

18053-Vicksburg Junior High School / Report Number 008

One Jackson Place, Suite 250  
188 East Capitol Street  
Jackson, MS 39201-2100  
P 601.352.5411  
F 601.352.5362

Contract Paul Jackson & Son  
Date / Time 28 April 2020 / 1:30 PM  
Weather / Temp Overcast / 74 ° F  
Est % Complete 5%  
Sched Conformance + 00 days

161 Lameuse Street, Suite 201  
Biloxi, MS 39530  
P 228.374.1409  
F 228.374.1414

Work in Progress Mechanical Work  
Dirt Work  
Interior Demo  
Present at Site South Central Heating & Plumbing  
Dan Duvall, Paul Jackson & Son  
Paul Purser, DBA

Observations Arriving on site, I entered by main entry and noted a large amount of interior demo work at prior office area.

Walking the site, I see that ducting work is ongoing as well as dirt work. In speaking with the contractor, it seems that retaining wall work will be started within the next couple of weeks.

Items to Verify None

Action Required None

Report By:

Paul Purser, LEED AP  
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)  
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)  
Gary Bailey / Jason Stewart / Mark Pipper (BPM)  
Russ Blount / Candy Failor (DBA)  
Brandon McKay / Austin Newell (WGK)  
Jason Kackley / Al Guynes (GSK)  
Chris Green / Larry Scott (TPS)  
Tom Schaeffer / Tad Hoffpauir (SDG)



Figure 1 – Continued Dirt Work



Figure 2 – Entry Office area Demo Ongoing



Figure 3 – Duct runs installed



Figure 4 – Duct runs installed



Figure 5 – Ceiling Grid Installed at lower floor Hall



Figure 6 – Ceiling Grid at Lower Floor Bathrooms



Figure 7 – Demo of Structure Ongoing



Figure 8 – Dirt Work Erosion



Figure 9 – Extent of Site Work



Figure 10 –Dirt Excavation for New Retaining Wall