

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

04 September 2020

18053-Vicksburg Junior High School / Report Number 018

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 02 September 2020 / 3:30 PM
Weather / Temp Partly cloudy / 93 ° F
Est % Complete 48%
Sched Conformance + 00 days
Work in Progress Footing Install
Present at Site Jeff Porter, PJS
Paul Purser, DBA

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Observations Arriving on site, I noted the final phases of footing installs at the front addition. Concrete was in the ground and areas were being tidied.

At the interior painting at the interior corridor is ongoing.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer / Tad Hoffpauir (SDG)



Figure 1 – Footing Install Ongoing



Figure 2 – Footing Install Ongoing



Figure 3 – Footing Install Ongoing



Figure 4 – Footing Install Ongoing



Figure 5 – Footing Install Ongoing



Figure 6 – Paint at Interior Corridor



Figure 7 – Paint at Interior Corridor



Figure 8 – Paint touch Ups Still Required



Figure 9 – Paint touch Ups Still Required



Figure 10 – Paint touch Ups Still Required



Figure 11 – Some Area only Appear to have a Single Coat



Figure 12 – Paint touch Ups Still Required



Figure 13 – Paint at Interior Corridor



Figure 14 – Exterior Build Site