

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

23 June 2021

18053-Vicksburg Junior High School / Report Number 035

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son

Date / Time 22 June 2021 / 1:30 PM

Weather / Temp Clear / 91 ° F

Est % Complete 80%

Sched Conformance + 00 days

Work in Progress Metal Rail Installation, Elevator Trim Work, Mechanical Work

Present at Site Jeff Porter, PJS
Paul Purser, DBA

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Observations On site, I entered by the main entry. The temporary construction barrier has been removed in this area and finishing work is ongoing here. The Space is fully conditioned except for the stairwell to the south, which has a temporary plastic barrier.

In the existing building, workers at the elevator are installing metal trim at the door opening.

Also, metal workers appear to be ready to set the new handrail at the central grand stair.

Items to Verify None

Action Required None

Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Jeff Porter / Kipp Ready (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer / Tad Hoffpaur (SDG)



Figure 1 – Temporary Structure Removed



Figure 2 – Bulk Head Finishing Work



Figure 3 – What is the plan for making up this height difference?



Figure 4 – Paint at office Nearing Completion



Figure 5 – Elevator Trim Install is Ongoing



Figure 6 – Rail Installation is Ongoing