

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

13 March 2020

18056-Warren Central Junior High School / Report Number 002

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 12 March 2020 / 1:16 PM
Weather / Temp Sunny and clear / 76 ° F
Est % Complete 2%
Sched Conformance + 00 days
Work in Progress Ceiling Demo

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Tommy Stewart (PJS)
Paul Purser, DBA

Observations Arriving on site, a Mr. Ambros (PJS). He was at work in the library finishing up ceiling demo. I noted for the most part, ceiling demo has been complete.

All areas that have been worked were clean save the area that Mr. Ambros was working.

There are several pallets of ceiling tile on the back drive. Are these to be removed by a piece of equipment. What's the timeline?

Items to Verify None

Action Required None

Report By:

Paul Purser, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Tim Wilson / Kipp Ready (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer (SDG)



Figure 1 – Backflow Installation On Going



Figure 2 – Upper Floor Ceiling Demo



Figure 3 – Cafeteria Ceiling Demo




Figure 4 – Library Ceiling Demo



Figure 5 – Side Halls Ceilings Demoed



Figure 6 – Hall Demo



Figure 7 – 2nd Floor Ceiling Demo




Figure 8 – 2nd Floor Ceiling Demo



Figure 9 – 1st Floor Ceiling Demo



Figure 10 – Demolded Tiles Stored: What is the timeline for removal?