

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

29 April 2020

18056-Warren Central Junior High School / Report Number 007

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 28 April 2020 / 2:00 PM
Weather / Temp Overcast / 74 ° F
Est % Complete 5%
Sched Conformance + 00 days
Work in Progress Sewer Work
Duct Installation
Interior Building Demo
Awning Install

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Jay Wilson, Paul Jackson & Son
Paul Purser, DBA

Observations Arriving, I entered the site at the West Entry. I noted duct installation was ongoing. Also, Demo work at the lower floor has begun at TLT B-103.

At the front entry to the main floor, Plumbing Work is being performed. Oak trees have been removed and demo at the existing façade is ongoing.

Items to Verify None

Action Required None

Report By:

Paul Purser, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Tim Wilson / Kipp Ready (PJS)
Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer / Tad Hoffpaur (SDG)



Figure 1 – Overcuts should be filled with a Cementous material



Figure 2 – Finished Awning



Figure 3 – Duct Runs installed at upper floor



Figure 4 – Duct Runs installed at upper floor



Figure 5 – Demo at lower floor Brick Wall Begun



Figure 6 – Entry Addition Work Ongoing



Figure 7 – Entry Addition Work Ongoing



Figure 8 – Entry Addition Work Ongoing