

Architect's Field Report

201 Park Court, Suite B	08 May 2020	
Ridgeland, MS 39157 P 601.790.9432	18056-Warren Central Junior High School / Report Number 008	
F 888.281.0547	Contract	Paul Jackson & Son
One Jackson Place, Suite 250	Date / Time	07 May 2020 / 12:00 PM
188 East Capitol Street	Weather / Temp	Clear / 74 ° F
Jackson, MS 39201-2100	Est % Complete	5%
P 601.352.5411	Sched Conformance	+ 00 days
F 601.352.5362	Work in Progress	Duct Installation Interior Finish Demo
161 Lameuse Street, Suite 201	Present at Site	Tim Wilson, Paul Jackson & Son
Biloxi, MS 39530		Paul Purser, DBA
P 228.374.1409	Observations	I arrived on site and noted that progress has been made at the sewer in
F 228.374.1414		the front of the building. I entered the building from the main entrance. There were workers putting together ducting in the main halls.
	Items to Verify	None
	Action Required	None

Report By:

Paul Purser, LEED AP Dale | Bailey, an Association

cc: Austin Stults / Tim Wilson / Kipp Ready (PJS) Chad Shealy / Shaquita Burke / Christi Kilroy (VWSD) Gary Bailey / Jason Stewart / Mark Pipper (BPM) Russ Blount / Candy Failor (DBA) Brandon McKay / Austin Newell (WGK) Jason Kackley / Al Guynes (GSK) Chris Green / Larry Scott (TPS) Tom Schaeffer / Tad Hoffpauir (SDG)

dalepartners.com baileyarch.com Architects Who Know Education



Figure 1 – Sewer work at Front Entry of Project in preparation for Addition



Figure 2 – Sewer leaving main building



Figure 3 – Sewer discharge to Street




Figure 4 – Added Pipes has been demoed back @ Room E-323A




Figure 5 – Mechanical Rough In is Ongoing



Figure 6 – Mechanical Rough In is Ongoing