

Architect's Field Report

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

16 June 2021

18056-Warren Central Junior High School / Report Number 024

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

Contract Paul Jackson & Son
Date / Time 15 June 2021 / 1:30 PM
Weather / Temp Sunny / 91 ° F
Est % Complete 80%
Sched Conformance + 00 days
Work in Progress Hardware Install
Alarm Installation
Mechanical Install

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Present at Site Jay Wilson, Paul Jackson & Son
Paul Purser, DBA

Observations On site, workers were installing hardware at the front entry. At the 1st floor, mechanical workers were installing ducting in locker room areas.

Items to Verify None

Action Required Make recommendation on Finishing Demoed Alarm Cabinet

Report By:

Paul Purser, AIA, LEED AP
Dale | Bailey, an Association

cc: Austin Stults / Tim Wilson / Kipp Ready (PJS)
Chad Shealy / Christi Kilroy (VWSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Candy Failor (DBA)
Brandon McKay / Austin Newell (WGK)
Jason Kackley / Al Guynes (GSK)
Chris Green / Larry Scott (TPS)
Tom Schaeffer / Tad Hoffpaur (SDG)



Figure 1 – Newly Install Concrete at Front Entry



Figure 2 – Stucco in Progress at Ceiling



Figure 3 – Fire Alarm Installers at Work Throughout



Figure 4 – Reference Panel during last OAC; (to be demoed, how to finish back?)



Figure 5 – Fire Alarm Installers at Work Throughout



Figure 6 – Mechanical Workers at Lower Level