

14 February 2023

21097 Greenwood Leflore Consolidated SD ESSER / Report Number 002

201 Park Court, Suite B
Ridgeland, MS 39157
P 601.790.9432
F 888.281.0547

One Jackson Place, Suite 250
188 East Capitol Street
Jackson, MS 39201-2100
P 601.352.5411
F 601.352.5362

161 Lameuse Street, Suite 201
Biloxi, MS 39530
P 228.374.1409
F 228.374.1414

Contract Upchurch Plumbing, Inc.
Date / Time 08 February 2023 / 2:30 PM
Weather / Temp Overcast / 68 ° F
Est % Complete 17%

Sched Conformance +/- 00 days

Work in Progress Fixture Install

Present at Site Upchurch Plumbing
Craig Bontrager, UpChurch
Paul Purser, DBA

Observations On site at Davis elementary, I met Craig Bontrager (Upchurch) at the rear of the site. Workers were installing fixtures throughout the newer section of Davis Elementary.

At Greenwood Middle, workers were installing toilet partitions. Uninstalled products appear to be in good/new condition.

Items to Verify None.

Action Required None

Report By:



paul purser, Architect
Dale | Bailey, an Association

cc: Brad Hawkins / Craig Bontrager / Scott Upchurch (Upchurch)
James Johnson-Waldington / Torien Howard / Cynthia House (GLCSD)
Gary Bailey / Jason Stewart / Mark Pipper (BPM)
Russ Blount / Sabrena Patrick (DBA)
Jason Kackley / Al Guynes (GSK)



Figure 1 – Upchurch parked at rear of Davis Elementary



Figure 2 – New Toilet Fixtures at Davis Elementary



Figure 3 – Insulation still needed in some areas



Figure 4 – New Fountains installed



Figure 5 – New Fountains installed



Figure 6 – Remove any construction markings



Figure 7 – Ensure that covers are fully secured



Figure 8 – Masonry dust from installation needs to be removed from brick face



Figure 9 – Partitions removed at Greenwood Middle



Figure 10 – Insulation Installed at Greenwood Middle



Figure 11 – Partition installation, starting at Greenwood Middle



Figure 12 – Partition installation, starting at Greenwood Middle